


Fig. 1
(PRIOR ART)






Fig. 3




Fig. 5

ABSOLUTE
POSITIONS OF
END STOPS
ARE ABOUT +30
AND -30 DEGREES
FROM REFERENCE

ABSOLUTE
POSITIONS OF
END STOPS
ARE ABOUT -30
AND +135 DEGREES
FROM REFERENCE

ABSOLUTE
POSITIONS OF
END STOPS
ARE ZERO AND
60 DEGREES
FROM REFERENCE




Fig. 4

